PEGASUS TRANSTECH

TRANSFLO Express®

Canon DR-6010C

Cleaning Instructions Manual

Document History			
Release Date	**Document Edition**	**File Name**	**Product Version**
12/14/2010	TFX-2.1-1.0-DP-EU	Canon DR-6010C Scanner Cleaning Instructions	2.1

Revision History		
Revision Date	**Owner/Modifier**	**Comments**
12/14/2010	Scott Kuhne	Draft

Table of Contents

1. Introduction

Overview

The Canon DR-6010C scanner is a TRANSFLO Express℠ supported scanner. This document describes the process for cleaning the DR-6010C scanner.

Prerequisites

Make sure you have the following ready before you start cleaning your scanner:

1. Soft clean cloth

2. Fellowes cleaning wipes or Windex

3. Compressed canned air

Cleaning Instructions

1. Turn the power off (power button on bottom, right front of scanner) and unplug the black power cord from the back of the scanner.

2. Carefully open the scanner cover by gently grasping the upper lid and swinging it up until it stops. Do not grasp the lid in the middle where the rollers are located. This can damage the rollers and cause feed problems.

3. Using the pre-moistened Fellowes cleaning wipes or a small amount of Windex on a soft cloth, wipe the scanning glass on the upper unit as well as the base unit of the scanner. Scratches on the glass can cause lines to appear on the images. If you have scratches that are causing lines contact your support department to have the glass replaced.

4. Use compressed air to blow the interior clean of dust and paper particles.
5. Dampen a soft cloth with water, wring it out thoroughly and wipe the rollers of the upper unit while turning them. Do not turn the rollers in the lower part of the scanner. Clean these rollers by simply wiping the exposed part.


Important:

Do not use detergent to clean the rollers. Any detergent residue on the rollers can cause feeding problems.

Do not try to turn the rollers in the bottom of the scanner. Doing so could cause damage that leads to feeding problems.

6. Remove the roller unit.

7. Remove the retard unit.

8. Wipe the removed rollers with a cloth moistened with water and thoroughly wrung out.
9. Replace both roller assemblies.

Document Comments

In order to provide the best documentation possible, your feedback and comments are very important to us. If you have any suggestions or comments, please complete the section below and mail or fax this form back to us at the address listed below.

_____

_____

_____

_____

_____

_____

_____

_____

_____

_____

_____

Product Documentation

Pegasus TransTech Corp.

4301 W Boy Scout Blvd.

Suite 550

Tampa, FL 33607

(813) 386-6500 (Fax)